



February 7, 2020

To the homeowners that are having their dryer vents cleaned.

When cleaned from the roof top down, the hose they are inserting is damaging the flap on the dryer vent. It is being broken or jammed and then not able to open and close as needed.

Dryer vents should be cleaned from the interior of the attic, exhaust pipes should be taken apart and cleaned downward and then upward as to not damage the flap.

Roof it Right